


Name: Urmila Rina Chohan.
 Department: Electronics Electrical Engineering
 Matric No: 171620-041069
 Electrical Machines Assignment.
 ENG 326

A 25KVA, 415V, three phase, 4 pole, 60Hz, wye connected synchronous generator has a synchronous reactances of 1.5Ω / phase and negligible stator resistance. The generator is connected to an infinite bus (of constant voltage magnitude and constant frequency) at 415V and 60Hz.

- Determine the excitation voltage, EA when the machine is delivering rated KVA at 0.8 pf lagging.
- The field excitation voltage current I_f increased by 20% without changing the power input from the prime-mover. Find the stator current I_a , power factor and reactive power Q supplied by the machine.
- With the field excitation current I_f as in part (a), the input power from the prime mover is increased very slowly, what is the steady state limit? Determine stator current I_a , power factor, and reactive power Q.

Solution

- $P = 25\text{KVA}$
- $p = 4 \text{ pole}$
- $f = 60\text{Hz}$
- $V = 415\text{V}$
- $X_s = 1.5\Omega$
- $r_s = 0$
- $Z = ?$
- $P = 0.8 \text{ pf}$



$$E_f = V_t = V_p \sqrt{3}$$

$$V_c = 415 \times \sqrt{3}$$

$$V_c = 718.8 \text{ V}$$

Recall
 $I_a = \frac{\text{Srated}}{V_c}$

$$= \frac{25000}{718.8}$$

$$= 34.78 \text{ A}$$

$$P.F. = 0.8 \text{ lagging}$$

$$P.F. = \cos \theta$$

$$0.8 = \cos \theta$$

$$\theta = \cos^{-1} 0.8$$

$$\theta = 36.9 \text{ (lagging)} \therefore I_a = 34.78 \angle -36.9^\circ$$

Recall $E_a = V_p + j X_s I_a$

$$E_a = 239.6 \angle 0^\circ + (1.5 \angle 90^\circ \times 34.78 \angle -36.87^\circ)$$

$$E_a = 274.0781 \angle 8.758^\circ \text{ A}$$

$$E_a = 270.902 + 41.735j \text{ A}$$

2. Real power of a synchronous motor is given as

$$P_{out} = \frac{3 \times V_p \times E_a \sin \delta}{X_s}$$

$$P_{out} = \frac{3 \times 239.6 \times 274.12 \times \sin(8.75)}{1.5}$$

$$= 19982.67003$$

$$\approx 20 \text{ kVA}$$

The ratio of rated power to real power:

$$\frac{25}{20} = 1.25$$

$$20$$

$$P_{rated} = 1.25 P_{out}$$

$$F_{a2} = 1.25 \times F_{a1}$$

$$= 1.25 \times 274.12$$

$$F_a = 342.65 \text{ V}$$

To Calculate Torque Angle (δ)

$$\frac{3V_s F_{a1} \sin \delta_1}{X_s} = \frac{3V_s F_{a2} \sin \delta_2}{X_s}$$

$$F_{a1} \sin \delta_1 = F_{a2} \sin \delta_2$$

$$\sin \delta_2 = \frac{274.12 \sin(8.75)}{342.65}$$

$$\sin \delta_2 = 0.12$$

$$\delta_2 = \sin^{-1}(0.12)$$

$$\delta_2 = 6.987^\circ$$

Recall

$$I_{\text{stator}} = \frac{F_{a2} - V_s}{X_s}$$

$$= \frac{342.65 \angle 6.987^\circ - 2396 \angle 0^\circ}{1.5 \angle 90^\circ}$$

$$I_{\text{stator}} = 72.5368 \angle -67.4^\circ$$

$$\text{Power factor} = \cos \theta$$

$$\text{where } \theta = 67.4^\circ$$

$$P.F. = \cos(67.4^\circ)$$

$$= 0.384 \text{ lagging}$$

For reactive power Q :

$$Q = \sqrt{3} \times V_L \times I_L \times \sin \theta$$

$$Q = \sqrt{3} \times 415 \times 72.5368 \times \sin(67.4^\circ)$$

$$Q = 48135.75$$

$$Q = 48 \text{ KVA}$$

Steady state limit is the maximum power transmitted without loss in transmission.

$$P_{max} = \frac{E_s \times V_r \times 3}{X_s}$$

$$= \frac{3 \times 239 \times 274.1}{1.5}$$

$$P_{max} = 131029 \text{ KVA}$$

$$= 131 \text{ KVA at } 90^\circ$$

- Stator current at SSL

$$I_{A \text{ stator}} = \frac{E_s - V_r}{X_s}$$

$$\Rightarrow \frac{274.12 \angle 90^\circ - 239 \angle 0^\circ}{1.5 \angle 90^\circ}$$

$$= 242.66 \angle 41.17^\circ$$

- Power Factor

$$P.F. = \cos \theta$$

$$P.F. = \cos(41.17)$$

$$= 0.752 \text{ leading}$$

Reactive Power

$$Q = \sqrt{3} \times V_r \times I_L \times \sin \theta$$

$$Q = \sqrt{3} \times 415 \times 242.66 \times \sin(41.17)$$

$$Q = 114822$$

$$= 115 \text{ KVA}$$